

NATURAL RUBBER LININGS				
TDS #	Color	Durometer	Cure Method	Description
RS-0010	Tan	36 +/- 5 Shore A	All	Soft Pure Gum - FDA / High Sat. HCL
RS-PN10	Tan	35 +/- 5 Shore A	All	Soft Pure Smoked Gum NR - FDA / HCL
RS-0013	Tan	40 +/- 5 Shore A	All	Soft NR - High Abrasion / Corrosion
RS-0014	Red	40 +/- 5 Shore A	All	Soft NR - High Abrasion / Corrosion
RS-0016	Black	40 +/- 5 Shore A	All	Soft NR - High Abrasion / Corrosion
RS-0017	Tan	40 +/- 5 Shore A	All	Soft NR - High Abrasion / Corrosion FDA
RS-0018	Black	60 +/- 5 Shore A	A - IP	NR/SBR - High Abrasion / Molding
RS-3333	Green	40 +/- 5 Shore A	All	Soft Premium NR - High Abrasion / Corrosion
RS-3801	Red	40 +/- 5 Shore A	All	Soft Premium NR - High Abrasion / Corrosion
RS-3802	Black	40 +/- 5 Shore A	All	Soft Premium NR - High Abrasion / Corrosion
RS-3858	Blue	40 +/- 5 Shore A	All	Soft Premium NR - High Abrasion / Corrosion
RS-4001	Black	60 +/- 5 Shore A	All	Soft NR - High Abrasion
RS-4002	Black	70 +/- 5 Shore A	All	Soft NR - High Abrasion
RS-4003	Black	60 +/- 5 Shore A	All	Soft NR - High Abrasion / UV and Ozone
RS-5506	Black	60 +/- 5 Shore A	All	Soft NR - High Abrasion
RS-5661	Charcoal	80 +/- 5 Shore A	All	Hard NR - FDA / Water Treatment

TRIPLY® SERIES LININGS				
TDS #	Color	Durometer	Cure Method	Description
RS-3000	Tan	55 +/- 5 Shore A	All	Soft/Semi-Hard/Soft NR / FDA
RS-3508	Black	60 +/- 5 Shore A	All	Soft/Semi-Hard/Soft NR / FDA
RS-3536	Black	60 +/- 5 Shore A	All	CIIR/Semi-Hard NR/CIIR / FDA

NEOPRENE® (CR) LININGS				
TDS #	Color	Durometer	Cure Method	Description
RS-0555	Black	50 +/- 5 Shore A	A - IP	Lead Cure CR - High Abrasion / Oil Sands
RS-9005	Black	60 +/- 5 Shore A	A - IP	Soft CR - High Abrasion / Oil Sands
RS-0545	Black	55 +/- 5 Shore A	A - IP	Lead Cure CR - High Abrasion / Oil Sands

NITRILE LININGS				
TDS #	Color	Durometer	Cure Method	Description
RS-2245	Black	45 +/- 5 Shore A	All	Soft NBR/NR - High Abrasion / Corrosion
RS-2265	Black	55 +/- 5 Shore A	A - IP	Soft NBR/NR - High Abrasion / Corrosion
RS-2275	Black	60 +/- 5 Shore A	A - IP	Soft NBR/NR - High Abrasion / Corrosion
RS-2276	Black	60 +/- 5 Shore A	A - IP	Soft NBR/NR - Anti-bacterial
RS-2277	Black	60 +/- 5 Shore A	All	Soft NBR/NR - MOR / FDA
RS-5705	Black	60 +/- 5 Shore A	A - IP	Soft NBR - Aliphatic Hydrocarbons

BUTYL LININGS				
TDS #	Color	Durometer	Cure Method	Description
RS-5510	Black	55 +/- 5 Shore A	All	Chlorobutyl - High Temperature / Corrosion
RS-5610	Black	60 +/- 5 Shore A	A - IP	Bromobutyl - High Temperature / Corrosion

Cure Methods: A (Autoclave) / IP (Internal Pressure) / Atph (Atmospheric)